

Trade-in your old plasma and DO MORE with Powermax®!

Cut with added reach



Cut flush to base metal



Cut in hard to reach places



	Powermax30 XP	Powermax30 AIR	Powermax45 XP	Powermax65 SYNC [®]	Powermax85 SYNC	Powermax105 SYNC	Powermax125
Recommended handheld capacity Thickness	3/8"	5/16"	5/8"	3/4"	1"	1-1/4"	1-1/2"
Severance	5/8"	5/8"	1-1/8"	1-1/4"	1-1/2"	2"	2-1/4"
Maximum mechanized pierce capacity	Not applicable	Not applicable	1/2"	5/8"	3/4"	7/8"	1"
Output current	15–30 A	15–30 A	10–45 A	20–65 A	25–85 A	30–105 A	30–125 A
Part number	088079	088096	088112	083343	087183	059625	059536

Trade-in values from \$230.00 to \$1,180.00.

Contact your S.J. Smith representative for details. Call 563-324-5237, or go to sjsmith.com. To find your local branch, go to sjsmith.com/our-company/locations.



PLASMA CUTTING SAFETY

★ ★ ★
**ARE YOU
PROTECTED?**
★ ★ ★

Don't get burned!

Is there a fire extinguisher nearby? Are flammables at least 35 feet away?

Never point the torch toward yourself or others. Let metal cool before touching it.



Stay grounded!

Is your work cable securely attached to the workpiece/ table with good metal-to-metal contact?

Don't connect to the piece that falls away.



Avoid toxic fumes!

Are there hazardous coatings or toxic materials?

Ensure adequate ventilation or use a respirator.

Don't get shocked!

Never touch the torch body, workpiece or water when the plasma system is operating on a CNC table.

